# This Page Is Inserted by IFW Operations and is not a part of the Official Record

#### **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.


Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

### IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.

LUMIMAIRE
INVENTOR: BARRY WHITE, et al.
SN: 10/616,743; DOCKET NO.: 0331
ATTY: DONALD E. HASSE; PHONE: (513) 229-0383



LUMIMAIRE INVENTOR: BARRY WHITE, et al. SN: 10/616,743; DOCKET NO.: 0331

SN: 10/616,743; DOCKET NO.: 0331 ATTY: DONALD E. HASSE; PHONE: (513) 229-0383




FIG. 2

#### LUMIMAIRE NVENTOR: BARRY WHITE

INVENTOR: BARRY WHITE, et al. SN: 10/616,743; DOCKET NO.: 0331

ATTY: DONALD E. HASSE; PHONE: (513) 229-0383




FIG. 3

LUMIMAIRE INVENTOR: BARRY WHITE, et al.
SN: 10/616,743; DOCKET NO.: 0331
ATTY: DONALD E. HASSE; PHONE: (513) 229-0383






FIG. 4

LUMIMAIRE
INVENTOR: BARRY WHITE, et al.
SN: 10/616,743; DOCKET NO.: 0331
ATTY: DONALD E. HASSE; PHONE: (513) 229-0383




FIG. 5